

May 19, 1989

TO: Wayne Hedberg, Permit Lead
FROM: Holland Shepherd, Soils Rec. Spec.
Re: May 15, 1989 Response, Crystal Peak Minerals Corp.,
M/027/008 - 89(1), Millard County, Utah
R613 - 004 - 106.6 and 107.5 - Operation Plan and Practices

The Division requires that the operator protect and stabilize stockpiled topsoil material. The topsoil stockpile should be seeded with an interim seed mixture (use the same or similar seed mix as that found in the original plan). The operator should also mark the stockpile as "topsoil" so that it is not mistaken for fill material.

hs
MN4/125